sampleTRAX SF Analytical Station



Status Indicator Light

Alerts user to system problems (leaks, empty reagents, etc...)

ULPAClean 10 Filter *(Optional)*

ULPA filtered environment

Ultra-clean Enclosure Exhausted with Air Shower

With exhaust vents and inert-gas air shower

sampleTRAX SF Autosampler

With barcode scanning and PFA probe and Fluoronetics rail

Fluorocapper

Automatic bottle uncapping for optimal results

High Purity PFA Reservoirs

With integrated level sensors

Wheels

Allows for flexible positioning

Integrated Computer Monitor with Swivel Arm

-Convenient, protected location for instrument computer

-Touch screen

ICP or ICPMS

Inert, Acid-Resistant HDPE Countertop

Integrated prep*FAST* S System

With ultra high purity syringes and valves

Vacuum Pump Storage Chamber

With pull out drawer for easy access

Leak Sensors

Detects leaks and alerts user